Isolating Connectors

700PARTD1

1.6





GENERAL PRODUCT INFORMATION:




This product is suitable for indoor dry locations only.

This product is intended to be used with Tech Lighting Kable Lite system only.





Loosen (Do Not Remove) the six #4-40 set screws with the provided 0.05 Allen wrench to clear the side holes.



Feed end of one Kable Lite cable half way into the side hole of the isolating connector and tighten the three #4-40 set screws with the 0.05 Allen wrench.

Feed the other Kable Lite cable half way into the other end of the isolating connector and tighten the three #4-40 set screws with the 0.05 Allen wrench.

Repeat steps 1 through 3 for the other isolating connector.

SAVE THESE INSTRUCTIONS!



© 2008 Tech Lighting, L.L.C. All rights reserved. The "Tech Lighting" graphic is a registered trademark of Tech Lighting, L.L.C. Tech Lighting reserves the right to change specifications for product improvements without notification. A Generation Brands Company